# AV2 A New Building for Avon Valley Indoor Bowls Club

1301(RP)001 Feasibility Study May 2014



**Bennetts Associates**Architects



'This is as much a safe and nurturing social club as a bowls facility'

Malcolm George

Development Director

#### **Document Control**

**Document Title** 1301(RP)0001 Feasibility Study

Contributions

Name Alastair Bogle

Company Bennetts Associates Architects

Location London

Revision \

Date 23th May 2014

Details First Issue

**Revision** 0

Date 13th May 2014

Details Second Draft Issue for Comment

**Revision** 00

Date 7th March 2014

Details Draft Issue for Comment


Authorisation

Name Julian Lipscombe

Title Director

Address Bennetts Associates Architects

I Rawstorne Place London ECIV 7NL



# Executive Summary

Bennetts Associates are delighted to produce this feasibility study for the Avon Valley Indoor Bowls Club. This study has explored the options for the creation of an exemplar facility, on a new site to meet the future aspirations of AVIBC.

It is envisaged this document will be used to clarify the club's vision and business case, but also facilitate the next stage of engagement with relevant stakeholders in order to fund and develop this exciting project.

This document contains information about the club, their future vision, and potential options for a new Bowls facility. Sweetts group have also contributed with an outline cost analysis to assist the Club with the next stages of development. AVIBC is a proactive and important presence in the Warwickshire community with a mission to help people live longer and lead more fulfilling lives. Bennetts Associates have enjoyed compiling this study and hope it provides the springboard for this overall objective to be obtained.

### Chairman's Statement

These are both extremely difficult and incredibly exciting times. We are very disappointed to leave our current building, but the opportunity to create a much improved facility could be fantastic. AVIBC is grateful to Bennetts Associates and Sweetts for their enthusiastic work on this document and to Jaguar Land Rover for financing this work. We must all work together to ensure that our club has a long term future, enabling future generations to enjoy all the benefits of playing indoor bowls.

Tony Thurlbeck Chairman AVIBC

### The Club

AVIBC has been a successful club for 40 years. It is run and a strong presence in the local community. The Club currently has a membership of just fewer than 500, made up of residents from the local area who play at club, district, county, national and international level. It is run and managed by it's members and has a proven track record with great potential for growth.

AVIBC currently operates from the Jaguar Landrover site in Gaydon, with the facility being partly constructed from the old officer's mess, a legacy of the old RAF base that used to be on site. Its current facilities consist of:

- A 6 rink playing surface split by columns due to the structure of the building
- 2 Changing rooms
- A bar and lounge facility
- A small multi-functional room for conferences/ events
- An office
- A kitchen and associated ancillary spaces.

Jaguar Land Rover have informed AVIBC that their current lease, which runs to 2020, will not be renewed. The club see this as the opportunity to create a new facility elsewhere that meets with their own aspirations and that of the English Indoor Bowling Association, which are:

- A growth in participation across the adult population in the local communities. Targeted to work to increase female participation
- A growth in participation in the 14-25 range, plus working with primary schools
- The provision of an excellent sporting experience for new and existing participants
- A growth in Indoor Bowls participation by people who have disabilities.











Existing Avon Valley Indoor Bowls Club Photographs

### The Vision

AVIBC are currently looking for a new site to house a new exemplar facility that can meet the aspirations of AVIBC and serve the local community. The club have outlined their vision with these key development as follows:

- To provide a centre of excellence for bowls all year round
- To provide bowling opportunities within a nurturing social environment for all age groups
- To help make bowls the number one participant sport for people aged over 55 years
- To provide a facility to enable disabled members of the community to compete in an active sport on as near equal terms as possible
- To provide for wider community use
- To increase membership by at least 75%
- To increase usage of the building by at least 50%
- To seek both strategic and suitable operational partners
- To obtain funding to relocate the facility

#### **Outline Brief**

With regard to a new bowls facility, the club's vision is for an economical, high quality building. A list of requirements has been recorded for a new "Gold Standard" facility the club would wish for cost permitting. These are as follows:

- Ceiling Height of approximately 5-6 meters
- A flat soffit with consistent finishes to avoid distraction
- 8 Rinks of standard size for bowls
- 4 Changing rooms 50 pegs/locker spaces
- Multi-functional room for recreational/meeting purposes
- Gym
- · An energy efficient building
- Approximately 3500m²
- Office
- Parking for 120 cars
- Disabled access throughout
- Viewing from 2-3 sides
- Kitchen, Bar/ Lounge facility
- Visible entrance





Potential vision for a new bowls facility


#### Sustainability

Sustainability forms and integral part of the brief for AVIBC and Bennetts Associates is a leader in sustainable design. A core principle behind the firms work is that sustainability is not merely an aspiration, but must be backed up in demonstrable facts. We develop a set of explicit criteria and targets at the outset of a project, and a range of management tools during its inception, in order to assist in achieving exemplar performance in sustainability in energy conservation.

Any further support from Bennetts Associates for the continuation of this project with the AVIBC would include these core principles from the onset.

#### **Materials**

The materiality of each project is individual and related to the specifics of the site, the desires of the client, and the sustainability agenda. Further development with the Avon Valley IBC and key stakeholders would be required to provide the highest standard and appropriate building for its users.







Suggested material pallette (to be developed)

### Club and Community

The clubs current and envisaged location is conveniently situated between multiple urban centres of Royal Leamington Spa, Warwick, Statford-upon-Avon, Kenilworth, Southam and Banbury. The metropolitan City of Coventry is also close by. The area is blessed with excellent transport links. This location gives AVIBC great scope for wider community engagement across the entire country and potential to grow its membership.

Location	Miles to AVIBC
Stratford-upon-Avon	16.4
Kenilworth	17.4
Warwick	8
Leamington	9
Southam	7.6
Kineton	3.9
Banbury	11

As stated previously the club see themselves as just as much a social club as a bowls club, and would be keen to grow this aspect in their new location. They are keen to retain their members and provide a safe environment where people feel comfortable and welcomed. The new facility would be seen as both a members bowls club, but also a welcoming public facility for socialising and events.

Their current arrangement with the Royal National Institute of the Blind, whom they host on a weekly basis, is a good example of this and the club and would be keen to develop further partnerships within the wider community to help develop this project.

#### Suggested interested parties could include:

- Royal National Institute of the Blind
- Bowls Development Alliance
- EIBA
- Bowls England
- Sport England
- CSW Sport
- NHS
- Age UK
- Warwickshire Schools













# Options Explored






#### The Rink


The most important element for a new bowls facility must be the playing surface itself. A specialist rink designer would need to be engaged in order to create this, but for the purposes of exploring options we have taken guidance of standard rink sizes from Sport England. Our options have explored the possibility of creating a facility that matches the base aspirations of the club, improves on the current facilities, and develops this further to create a "Gold Standard" solution that builds on the principles of a base scheme.

To start we have a rink run 36.5 m long with individual rinks of 4.8m wide with associated ditches around. There is a 1.8 zone for circulation and the intention of a viewing area from 3 sides.

#### **Base Scheme**

A base scheme would lay out two blocks of accommodation in an L shape around the rinks. This would naturally create a distinction between the private areas- the changing room's, committee room, and rink access- and the more public functions like the bar and function rooms. The corner where they overlap can be used for shared facilities such as the office, toilets and ancillary functions.





#### Gold Standard


By placing two rinks on the end of the building, but rotated 90° the gold standard aspiration of 8 rinks could be achieved. This proposal would not increase the width of the building, thus increasing the structural span, which could potentially reduce the overall cost. As a result the layout of the accommodation can remain unchanged.

#### **Gold Standard Long Span**

Alternatively if the 8 rinks are placed in one run together the playing surface will be one consistent surface, but the overall building will become wider as a result. If this solution is sought extra space can be created to add a gym facility although this would potentially require the reconfiguration of the changing rooms to accomodate these extra facilities.

Both Gold standards would provide 8 rinks which is suitable for international play, however, for the majority of the time two would be used for training, community use or pay & play, allowing competitive bowls to remain unhindered on the remaining six.

### Structure




#### **Portal Frame or Flat Beam Solution?**

The design of the structure will need to be clarified by a professional structural engineer. It will be important to achieve the most economical solution, in order to provide the desired floor to ceiling height between 5-6m, with a playing space and view that is unimpeded by columns. The Sport England design guide suggests a steel portal frame, but a flat beam solution could be possible depending on the length of the span. A line of secondary columns may also be required, but consideration would be needed to not let this effect the viewing of the bowls. For the purposes of the options a portal frame has been considered on a 5 meter grid.

#### **Base Scheme**

A notional grid of 5m has been considered with the primary span of the portal (in red) being 43m. A line of secondary structure has been inserted 10m from the primary structure to define the playing surface from the accommodation areas. If required, this would still ensure a column free space around the playing surface. The design has been developed though the principle of the playing and viewing of the game is the most important aspect, with the bar lounge located to the side to reduce movement behind the bowlers arm.



#### **Gold Standard**

Due to its design, the gold standard has no overall increase in primary span length. It requires 3 more bays of 5m structure to accommodate the two extra rinks. Although this structure meets the gold standard for rink provision it could potentially create an issue with the secondary structure if required.


#### Gold Standard Long Span

This structure would provide a space large enough to have all 8 rinks on one playing surface, but would increase the length of span to 52m. This arrangement does however create the additional area that could be used for a gym as per the brief. This design represents the maximum scheme that accommodates all of the desired brief elements and has 8 rinks on a single playing surface.

# Illustrative Proposals

The following drawings detail the three proposals on a generic site that meets the clubs varied aspirations. Further analysis and engagement with the appropriate structural and cost consultants, would be required to develop any of the following proposals in conjunction with identification of an appropriate site. The intention would be whichever route AVIBC pursue, any of the following proposals would provide an outstanding facility to meet their vision.


#### Site Plan




### Base Scheme

#### **Base Scheme**

The base scheme represents a 6 rink option that matches and improves on the current accommodation the AVIBC have. Its aim would be to have a reduce scale option for cost purposes that would be an exemplar facility for the club, but also of benefit to the wider community.




Internal view over playing surface from raised circulation zone (red dot on plan indicated viewpoint)




### Gold Standard

#### **Gold Standard**

The Gold Standard scheme builds on the principles of the base design, but allows for the extra 2 rinks requested through clever use of the overall span of the building structure. It is envisaged this could be an economical way of obtaining the 8 rinks AVIBC desire, though thorough cost analysis would be required. The difference in size is represented by the red marked area on the plan.




Internal view over playing surface from raised circulation zone (red dot on plan indicated viewpoint)




# Gold Standard Long Span

#### **Gold Standard Long Span**

This scheme represents the maximum option that would accommodate the entire brief in a single long span structure. This is potentially the least economical cost solution to meet the brief. The benefits of this scheme would be the consolidation of all the rinks on one surface, with extra area created for a small gym or similar facility. The difference in size is represented by the red marked area on the plan.



Internal view over playing surface from raised circulation zone (red dot on plan indicated viewpoint)



## Comparison

The following table represents a comparison between the three schemes in order for further analysis from the appropriate structural, services, and cost consultants.

	Base Scheme	Gold Standard	Gold Standard Long Span
Footprint Area (Approx m²)	2200	2900	2700
Longest Span	33	33	43
No. Rinks	6	8	8
Building Dimensions (m)	50 x 43	65 x 43	50 x 53
Portal Grid spacing (m)	5	5	5
Floor to ceiling height (m)	5.5	5.5	5.5
Office			
Committee Room			
Bar + Lounge			
Kitchen			
Level Disabled Access			
No. Viewing Areas	3	5	3
No. Changing Rooms	4	4	4
Multi-Function Space			
Gym			

Below is a indicative cost report compiled by Sweetts for each proposal. While only initial, and further information would need to be gathered for a full cost analysis, this report is invaluable in identifying and clarifying AVIBC's aspirations for a new facility.

EXECUTIVE SUMMARY				
	£	GIFAs	£/m2	£/sq ft
Base Scheme	3,272,000 **	2,200 m²	£1,487 m²	£138 ft²
Gold Standard	3,970,000 **	2,900 m²	£1,369 m²	£127 ft²
Gold Standard Long Span	3,819,000 **	2,700 m²	£1,414 m²	£131 ft²

#### \* Exclusions:

Pre-Opening Costs Financing Costs Additional Fees & Charges Inflation past 2016 VAT See also Section 3.0 of this report

Project Description The project involves the construction of a new centre for the Avon Valley Indoor Bowls Club

Project Duration TBA

Inflation Allowances Costs are at current day however an inflation allowance is included

Contingency 10% for design & construction


Basis of Cost Plan \*\* For further expansion of notes, exclusions and assumptions, reference should be made to the main body of this report

#### 2.0 CALCULATION SHEET

BUDGET PROPOSALS FOR THE NEW AVON VALLEY INDOOR BOWLS CLUB	BASE SCHEME		GOLD STANDARD					STANDAI NG SPAN	RD			
Nr CATEGORY  GIFA = Gross Internal Floor Area	QUANT GIFA	MODE	RATE £	TOTAL £	QUANT GIFA	MODE	RATE £	TOTAL £	QUANT GIFA	MODE	RATE £	TOTAL £
1 Substructure	2 200	2	4	0.000	2 000	2		17.400	2 700	2		16 200
a Ground preparation b Excavation and filling	2,200 2,200	m2 m2	4 5	8,800 11,000	2,900 2,900	m2 m2	6 5	17,400 14,500	2,700 2,700	m2 m2	6 5	16,200 13,500
c Stanchion bases	2,200	m2	8	17,600	2,900	m2	8	23,200	2,700	m2	10	27,000
d Concrete slab and upstands	2,200	m2	30	66,000	2,900	m2	30	87,000	2,700	m2	30	81,000
e Perimeter foundations	2,200	m2	10	22,000	2,900	m2	10	29,000	2,700	m2	10	27,000
f Underground drainage g Incoming services - builders works	2,200	m2	12	26,400 4,200	2,900	m2	12	34,800 4,200	2,700	m2	12	32,400 4,200
2 Superstructure												
A Frame												
a Primary steel frame b Secondary steel frame	2,200 2,200	m2 m2	70 9	154,000 19,800	2,900 2,900	m2 m2	70 9	203,000 26,100	2,700 2,700	m2 m2	77 9	207,900 24,300
c Framing for openings	2,200	m2	7	15,400	2,900	m2	7	20,300	2,700	m2	7	18,900
B Roof												
a Coverings and linings	2,200	m2	65	143,000	2,900	m2	65	188,500	2,700	m2	65	175,500
b Openings	2,200	m2	25	55,000	2,900	m2	25	72,500	2,700	m2	25	67,500
c Edge details d Rainwater gutters and downpipes	2,200 2,200	m2 m2	4 6	8,800 13,200	2,900 2,900	m2 m2	4 6	11,600 17,400	2,700 2,700	m2 m2	4 6	10,800 16,200
e Man-safe system	2,200	m2	3	6,600	2,900	m2	3	8,700	2,700	m2	3	8,100
C External walls	,			-,	,			.,	,			-, -
a Masonry inner and outer skins	2,200	m2	60	132,000	2,900	m2	60	174,000	2,700	m2	60	162,000
b Wind posts	2,200	m2	5	11,000	2,900	m2	5	14,500	2,700	m2	5	13,500
D External doors and windows				C 500				10.000				10.000
a Entrance doors b Other external doors				6,500 4,200				10,000 4,200				10,000 4,200
c Windows	2,200	m2	18	39,600	2,900	m2	18	52,200	2,700	m2	18	48,600
d Other glazing; screens	,			17,500	,			17,500	,			17,500
E Internal walls												
a Masonry walls	2,200	m2	8	17,600	2,900	m2	8	23,200	2,700	m2	8	21,600
b Stud and plasterboard walls  F Internal doors	2,200	m2	20	44,000	2,900	m2	20	58,000	2,700	m2	20	54,000
F Internal doors a Fire resistant doors and linings				17,200				17,200				17,200
b Doors and linings				25,680				25,680				26,580
c Internal glazed screens				18,000				18,000				18,000
d Shutters for bar counters				8,500				8,500				8,500
G Finishes												
a Bowling surface	2,200	m2	34	74,800	2,900	m2	34	98,600	2,700	m2	34	91,800
b Other floor finishes	2,200	m2	24	52,800	2,900	m2	24	69,600	2,700	m2	24	64,800
c Wall finishes d Ceiling finishes	2,200 2,200	m2 m2	16 45	35,200 99,000	2,900 2,900	m2 m2	16 45	46,400 130,500	2,700 2,700	m2 m2	16 45	43,200 121,500
H FF&E	2,200		.5	33,000	2,500		.5	130,300	2,700		.5	121,500
a Benching for changing rooms				6,000				6,000				6,000
b Tables and chairs to office and mtg room				2,000				2,000				2,000
c Lockers				6,400				6,400				6,400
d Bar counters and backfittings				20,000				20,000				20,000
e Storage shelving and fittings f Kitchen fixtures and equipment				2,000 43,000				2,000 43,000				2,000 43,000
g Other white goods				4,000				4,000				4,000
h Signs - information and mandatory				4,500				4,500				4,50
j Viewing space seating				21,000				33,000				26,00
k Accommodation of gym equipment												7,80
J Mechanical, Electrical and Public Health Services						_			2	-		
a Mechanical services	2,200	m2	45	99,000	2,900	m2	45	130,500	2,700	m2	45	121,50
b Public health supplies c Public health waste and disposal	2,200 2,200	m2 m2	9 5	19,800 11,000	2,900 2,900	m2 m2	9 5	26,100 14,500	2,700 2,700	m2 m2	9 5	24,30 13,50
d Sanitary appliances and fittings	2,200	m2	6	13,200	2,900	m2	6	17,400	2,700	m2	6	16,20
e Electrical services	2,200	m2	55	121,000	2,900	m2	55	159,500	2,700	m2	55	148,50
f Builders works in connection with services	2,200	m2		19,800	2,900	m2		26,100	2,700	m2		24,30
Overall rate per m2 GIFA =			£713				£697				£712	
3 External Works	5 700		•	45.050	F 700	2	_	45.050	F 700	- 3	•	45.65
a Site preparation and clearance	5,732	m2	8	45,856	5,732	m2	8	45,856	5,732	m2	8	45,85
b Incoming services and mains c Hard pavings	1,322	m2	55	30,000 72,710	1,322	m2	55	30,000 72,710	1,322	m2	55	30,00 72,71
d Soft landscaping around the perimeter	1,344	1112	JJ	5,000	1,344	mz	33	5,000	1,344	mz	33	5,00
e New car parking area	3,087	m2	75	231,525	3,087	m2	75	231,525	3,087	m2	75	231,52
f Reforming existing car park area	1,323	m2	45	59,535	1,323	m2	45	59,535	1,323	m2	45	59,53
g Perimeter fencing	205	m	85	17,425	205	m	85	17,425	205	m	85	17,42
h External lighting	5,732	m2	6	34,392	5,732	m2	6	34,392	5,732	m2	6	34,39
j Street furniture				7,500				7,500				7,50
k Site entrance modification I Underground drainage	5,732	m2	7	5,000 40 124	5,732	m2	7	5,000 40.124	5,732	m2	7	5,00 40,12
n Signage - main entrance and disclaimers	3,/32	1112	,	40,124 6,500	3,/32	IIIZ	,	40,124 6,500	3,/32	mz	,	40,12 6,50
4 Additions												
a Main Contractors preliminaries			12%	254,838			12%	309,222			12%	297,48
b Main Contractors overheads and profit			4%	95,139			4%	115,443			4%	111,06
c Contingency			10%	247,362			10%	300,151			10%	288,75
d Sustainability features			3%	81,630			3%	99,050			3%	95,29
e Inflation allowance (2016)			4% 15%	112,105			4% 15%	136,028			4% 15%	130,86
f Consultant fees (Allowance)			15%	356,773			15%	432,910			15%	416,48
GRAND TOTALS			_	3,272,000			_	3,970,000			_	

### The Vision









### Next Steps

The cost to build a new bowls facility is high and the availability of funding sources is scarce. It is clear that raising sufficient money for this new building is a very ambitious and difficult task. In addition to securing a site and financing the scheme, AVIBC needs to increase use of the existing facility and continue to attract new members.

AVIBC has significant financial reserves and some of this money will be used to finance the initial fund raising activity. A steering committee has been formed to govern the project and a part time project manager has been engaged to drive forward with the fund raising activity.

The first task is to convert the existing organisation into a charity which is necessary to secure maximum funding and tax benefits. Following the lengthy process of conversion to a charity, every possible source of funding will be investigated and pursued as appropriate. Promotion of our story in the media will be initiated at a time when the benefit is likely to be greatest.

It is critical that members of the club work together and develop a broad network of organisational / personal contacts from where financial assistance can be sought.



I Rawstorne Place London, ECIV 7NL T +44 (0)20 7520 3300 F +44 (0)20 7520 3333 mail@bennettsassociates.com 3 Boroughloch Square Edinburgh, EH8 9NJ T +44 (0) | 3 | 667 735 | F +44 (0) | 3 | 662 | 867 edin@bennettsassociates.com

www.bennettsassociates.com

